


MUNICIPAL COUNCIL BADE
BACHELI

DISTRICT SOUTH BASTAR DANTEWADA (C.G.)

PROFORMA REGARDING SAFE DRINKING WATER RAIN , WATER
HARVESTING AND SANITARY CONDITION

CERTIFICATE

No. 1419


Dated:02.03.2023

It is certified that an inspection team headed by GAURAV SAO SUB ENGINEER (CIVIL), Municipal council bade Bacheli (Name of Officers with designation) from Civil Dept. Municipal council BADE BACHELI (Name of Department/Office inspected the DAV PUBIC SCHOOL BACHELI-494553 (Name & Address of the School) On 2..03.2023 and found that the DAV PUBLIC SCHOOL, BACHELI (Name of School) has safe drinking water facilities for the students and as well members of staff of the institution and is maintaining the hygienic sanitation condition in the school building & the campus as per the norms prescribed by the Central/State/U.T. Govt.

The above valid for a period of **Three Year**.

The school building is also having rain water harvesting facility .

To,
Principal
DAV School, Bacheli
(Name o& Address of the Institution)


Sub Engineer
Municipal Council BADE BACHELI
Dist- South Bastar DANTEWADA (C.G.)
जि.द.प. दन्तेवाडा (उ.ग.)